



Sealing service for optical 6-Series sensors and EXO central wipers

Now available at ecoTech



YSI recommends to replace the wiper shaft seal of the 6-Series optical sensors and the internal seals of the EXO central wiper every 2 years. In the past this devices needed to be shipped to a YSI workshop which resulted in long turnaround times. Meanwhile after a specific training ecoTech had been approved to perform the sealing service in its own workshop in Bonn.

We strongly recommend this as a precaution as untight sensors and central wipers usually cause expensive repairs. In some cases a device even needs to be replaced by a new one. Usually the sealing service will be completed within one working day, so you don't have to wait a long time for your device. Please feel free to contact us and arrange an appointment.

Sealing service for optical YSI sensors (6-Series)

- Quad seal and bearing plug removal
- Wiper shaft cleaning and inspection
- Quad seal replacement and bearing plug installation according to YSI specifications
- Wiper rotation test
- Sensor test

Price: 89,- € net*)

Sealing service for EXO central wiper

- Initial check
- Replacement of all seals on the central wiper
- Final test

Price: 145,- € net*)

*) Price is effective until 12/31/2020, plus 19% VAT, shipping and insurance